

**DAILY WORK REPORT**

<b>DATE:</b> FEBRUARY 27, 2014	<b>TASK ORDER:</b> 0036	<b>PAGE</b> <u>1</u> <b>OF</b> <u>1</u>	
<b>WORK SITE NAME:</b> TURKEY BROOK OIL SITE		<b>WEATHER CONDITIONS:</b> SUNNY <b>TEMPERATURE:</b> 20	
<b>LOCATION (CITY, STATE):</b> OAKVILLE, CT		<b>MOBE/DEMOBE:</b>	<b>START TIME:</b> 0800 <b>STOP TIME:</b> 1300
<b>CONTRACTOR:</b> GUARDIAN ENVIRONMENTAL SERVICES <b>TEAM SUBCONTRACTORS:</b> SHAW ENVIRONMENTAL INC. TMC ENVIRONMENTAL		<b>RM:</b> MIKE QUINLAN <b>EPA OSC:</b> TED BAZENAS <b>START REP:</b> KEN ROBINSON	
<b>1. WORK AUTHORIZED BY OSC</b>		<b>WORK ACCOMPLISHED</b> <i>(DEFINE QUANTITIES IE, CUBIC YARDS TREATED, ETC.)</i>	
USE SKIMMER TO REMOVE OIL FROM SITE WELLS.		USED SKIMMER TO REMOVE OIL FROM TWO OF THE 2 INCH AND ONE 4 INCH WELL OUTSIDE THE BUILDING. THE 2 INCH WELL NEAR THE DOOR HAD APPROXIMATELY 1 FT OF PRODUCT AND THE OTHER 2 INCH WELL HAD APPROXIMATELY 0.5 FT OF PRODUCT. THE 4 INCH WELL HAD APPROXIMATELY 0.3 FT OF PRODUCT. ALL WELLS MEASURED LESS THAN 0.1 INCHES OF OIL IN THEM WHEN SKIMMING WAS COMPLETE.  THE NEWLY INSTALLED WELL INSIDE THE BUILDING ONLY HAD A SHEEN OF OIL ON TOP OF THE WATER COLUMN, THEREFORE NO SOIL WAS SKIMMED FROM THIS WELL.	
<b>2. NUMBER OF PERSONNEL AUTHORIZED (SEE WEEKLY WORK ORDER)</b>			
1	RESPONSE MANAGER 2	DBA OPERATOR	SCA OPERATOR
			DBA FORMAN
			1
			SCA FORMAN
	DBA LABORERS	SCA LABORERS	PBA (OFF SITE)
	1	1	TD COORD. (OFF SITE)
			CHEMIST (OFF SITE)
NOTE: TURKEY BROOK WAS PARTIALLY FROZEN, THEREFORE THE BOOM COULD NOT BE ACCESSED FOR MAINTENANCE.			
<b>3. EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED (SEE WEEKLY WORK ORDER)</b>			
ITEM	QTY	USED	DELIVERY DATE
PICKUP TRUCK	2	2	2/27/14
INTERFACE PROBE(RENTAL)	1	1	1/8/14
<b>4. SUBCONTRACTORS AUTHORIZED</b>			
<b>SUBCONTRACTOR NAME</b>		<b>SUBCONTRACTOR SERVICE</b>	
SIGNATURE OF OSC		SIGNATURE OF RESPONSE MANAGER	
DATE		DATE	